IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 10003590-1

IN RE APPLICATION OF: U.S. Patent No. 7,594,507

USPTO CONFIRMATION CODE: 5570

APPLICATION NO.: 09/761,287

FILED: Jan. 16, 2001

EXAMINER: DANTON DEMILLE

GROUP ART UNIT: 3771

FOR: THERMAL GENERATION OF DROPLETS FOR AEROSOL

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 09/761,287, now Patent Number 7,594,507.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

	I errors were the fault of the USPTO, no fee required. In the event that a further tired, please charge the amount to Deposit Account No. 082025.
to our De	Il errors were the fault of the applicant and, accordingly, please charge \$100.00 posit Account No. 082025. In the event that a further fee is required, please amount to the same Deposit Account.
please cha	ne errors were the fault of both the applicant and USPTO and, accordingly, arge \$100.00 to our Deposit Account No. 082025. In the event that a further feed, please charge the amount to the same Deposit Account.

The exact location where the error appears in the patent and patent application is as follows:

In column 10, line 41, in Claim 5, delete "0.35" and insert - - 0.35. - -, therefor. (Notice of Allowance and Fees Due (PTOL-85) dated Jul. 27, 2009, page 2, in claim 3, line 2)

The requested correction is attached on Form PTO 1050.

Respectfully Submitted

08/13/2010

DATE

/Yeh K Chang/

Name: Yeh K Chang Registration No.:41,397

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO.

: 7,594,507

APPLICATION NO.: 09/761,287

ISSUE DATE

: Sep. 29, 2009

INVENTOR(S)

: Colin C. Davis

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 10, line 41, in Claim 5, delete "0.35" and insert - - 0.35. - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Hewlett-Packard Company Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14 This collection is estimated to take 1.0 hour to complete, including gathering. preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Clivel Information Officer, U.S. Pateur and Trademark Office, U.S. Department of Commerce. P.O. Bux 1450, Alexandria, VA 22313-1459, DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS, SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450,